

# WEST Search History

[Hide Items](#) [Restore](#) [Clear](#) [Cancel](#)

DATE: Wednesday, February 20, 2008

<u>Hide?</u>	<u>Set Name</u>	<u>Query</u>	<u>Hit Count</u>
		<i>DB=PGPB,USPT; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>	L48	L47 and @pd > 20071218	8
<input type="checkbox"/>	L47	L45 or L36	565
<input type="checkbox"/>	L46	L45 not L36	160
<input type="checkbox"/>	L45	(passiv\$ or conversion) and L44 ((cr or chromium) near2 (plate or plated or plating)) and (((oxidized or oxide) near2 chromium) or chromia or chromate or "chromium oxide" or "chromium trioxide" or "chromium tri-oxide" or "cr tri-oxide" or "cr trioxide" or cr2o3 or "cr.sub.2o.sub.3") and "surface roughness"	237
<input type="checkbox"/>	L44	L38 and (passiv\$ or conversion)	953
		<i>DB=EPAB,JPAB,DWPI; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>	L42	L39 or L1 or L21	288
<input type="checkbox"/>	L41	L40 not L21	69
<input type="checkbox"/>	L40	L39 not L1	75
<input type="checkbox"/>	L39	(atmosphere or oxidiz\$) and L38 ((cr or chromium)) and (((oxidized or oxide) near2 chromium) or chromia or chromate or "chromium oxide" or "chromium trioxide" or "chromium tri-oxide" or "cr tri-oxide" or "cr trioxide" or cr2o3 or "cr.sub.2o.sub.3") and "surface roughness"	94
<input type="checkbox"/>	L38	L38 and (passiv\$ or conversion)	1286
<input type="checkbox"/>	L37	L32 or L34 L34 not L32 ((cr or chromium) near2 (plate or plated or plating)) and (chromate or "chromium oxide" or "chromium trioxide" or "chromium tri-oxide" or "cr tri-oxide" or "cr trioxide" or cr2o3 or "cr.sub.2o.sub.3") and "surface roughness"	1286
		<i>DB=PGPB,USPT; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>	L36	L32 or L34	405
<input type="checkbox"/>	L35	L34 not L32	35
<input type="checkbox"/>	L34	((cr or chromium) near2 (plate or plated or plating)) and (chromate or "chromium oxide" or "chromium trioxide" or "chromium tri-oxide" or "cr tri-oxide" or "cr trioxide" or cr2o3 or "cr.sub.2o.sub.3") and "surface roughness"	205
<input type="checkbox"/>	L33	L32 and @pd > 20070824	21
<input type="checkbox"/>	L32	L31 or L30	370
<input type="checkbox"/>	L31	(L28 or L27) not L30	152
<input type="checkbox"/>	L30	L29 or L25	218
<input type="checkbox"/>	L29	L28 not L25	9
<input type="checkbox"/>	L28	L22 and passivation	124

<input type="checkbox"/>	L27	L26 not L25	152
		((cr or chromium) adj2 (plate or plated or plating)) and (chromate or "chromium oxide" or "chromium trioxide" or "chromium tri-oxide" or "cr tri-oxide" or "cr trioxide" or cr2o3 or "cr.sub.2o.sub.3") and "surface roughness"	
<input type="checkbox"/>	L26	L25 or L11	168
<input type="checkbox"/>	L25	L23 not L11	209
<input type="checkbox"/>	L24	L23 and L22	2
<input type="checkbox"/>	L23	((cr or chromium)) and (chromate or "chromium oxide" or "chromium trioxide" or "chromium tri-oxide" or "cr tri-oxide" or "cr trioxide" or cr2o3 or "cr.sub.2o.sub.3") and "surface roughness"	19
<input type="checkbox"/>	L22	<i>DB=EPAB,JPAB,DWPI; PLUR=YES; OP=OR</i>	2876
<input type="checkbox"/>	L21	L19 or L16	219
<input type="checkbox"/>	L20	L19 not L16	48
		((cr or chromium)) and (chromate or "chromium oxide" or "chromium trioxide" or "chromium tri-oxide" or "cr tri-oxide" or "cr trioxide" or cr2o3 or "cr.sub.2o.sub.3") and "surface roughness"	
<input type="checkbox"/>	L19	L18 not L16	219
		((cr or chromium) adj2 (plate or plating or plated)) and (chromate or "chromium oxide" or "chromium trioxide" or "chromium tri-oxide" or "cr tri-oxide" or "cr trioxide" or cr2o3 or "cr.sub.2o.sub.3") and "surface roughness"	
<input type="checkbox"/>	L18	L17 or L15	0
<input type="checkbox"/>	L17	L16 not L1	8
		((cr or chromium) adj2 (plate or plating or plated)) and (chromate or "chromium oxide" or "chromium trioxide" or "chromium tri-oxide" or "cr tri-oxide" or "cr trioxide" or cr2o3 or "cr.sub.2o.sub.3") and "surface roughness"	
<input type="checkbox"/>	L16	chromium and (chromate or "chromium oxide" or cr2o3 or "cr.sub.2o.sub.3") and "surface roughness"	171
<input type="checkbox"/>	L15	<i>DB=PGPB,USPT; PLUR=YES; OP=OR</i>	10
<input type="checkbox"/>	L13	L12 and @pd > 20070307	171
<input type="checkbox"/>	L12	L11 and @pd > 20060622	34
<input type="checkbox"/>	L11	L10 or L9 or L8 or L7	52
<input type="checkbox"/>	L10	4520077[uref]	207
<input type="checkbox"/>	L9	L8 not L7	4
<input type="checkbox"/>	L8	(chromium and (chromate or "chromium oxide")) and "surface roughness" and passivation	106
<input type="checkbox"/>	L7	L6 or L3	115
<input type="checkbox"/>	L6	L4 not L3	97
<input type="checkbox"/>	L5	L4 not 3	17
<input type="checkbox"/>	L4	(chromium and (chromate or "chromium oxide")) and "surface roughness" and L2	0
<input type="checkbox"/>	L3	(chromium and (chromate or "chromium oxide")) and "surface roughness").clm.	17
<input type="checkbox"/>	L2	(427/331 or 427/337 or 427/372.2 or 427/377 or 427/383.1 or 427/383.3 or 427/383.7)[CCLS]	80
<input type="checkbox"/>	L1	<i>DB=EPAB,JPAB,DWPI; PLUR=YES; OP=OR</i>	6095
<input type="checkbox"/>	L1	chromium and (chromate or "chromium oxide") and "surface roughness"	161

END OF SEARCH HISTORY